

Sub Divisional Engineer, Samgra Shiksha Distt. Sirsa

Room no. 80A, Third Floor, Mini Sectt. Sirsa

Ref.No. : SS/Civil-2553

Dated : 19-05-2022

### BUILDING SAFETY CERTIFICATE

It is certified that The Gurukul School at Rania Distt. Sirsa has been inspected by undersigned along with JE, SS Block Rania. The school building have complied with building laws in accordance with rule of State. The Building is in sound, safe and stable condition. This is found structurally safe.

The building safety certificate is issued as per structural drawings submitted as designed by Sh. Gurmail Singh BE(Civil Engg.) AMIE, E4/15 AWCHS salunke vihar, Pune (Maharashtra) along with the case. The Responsibility of Construction as per structural drawing lies with the management of school.

*P/S*  
*J.E.*  
*19/5/2022*

*M. Singh*  
*19/5/22*  
*SDE*  
Samagra Shiksha  
SIRSA